



Environmental Impact Assessment Report

# Swarclett Wind Farm

Technical Appendix 10-2: Plates

Swarclett Wind Energy Limited

**wind2**

June 2024



# Contents

## Plates

- Plate 10-2-1: View south-southwest towards the southwest portion of Site, within the topographical setting of a former river valley
- Plate 10-2-2: View over existing track, facing east
- Plate 10-2-3: View over the northwest extent of the Proposed Development Site with clearance cairn (Asset 103) immediately adjacent to the boundary visible in left mid-frame, facing southwest
- Plate 10-2-4: Modern dismantled agricultural building (Asset 104), facing southwest
- Plate 10-2-5: Small clearance cairn, facing west
- Plate 10-2-6: Drainage ditch (Asset 106) under vegetation on right of ranging rod, facing southwest
- Plate 10-2-7: Spoil heap (Asset 107) under vegetation, facing southeast
- Plate 10-2-8: View northwest over Turbine 1 location
- Plate 10-2-9: View west from Turbine 1 location towards the Scheduled Stemster long cairn (Asset 9), visible in mid-frame skyline as low mound framed by larger reservoir mound to left and commercial forestry plantation to the right
- Plate 10-2-10: View southeast from Turbine 1 location towards the Scheduled Stone Lud (Asset 47), situated beyond (and below) intervening rise of hill
- Plate 10-2-11: Drystone wall (Asset 70a), facing southwest
- Plate 10-2-12: View northeast over building (Asset 70c) from southwest corner, ranging rod demarcating northeast corner
- Plate 10-2-13: View northeast over building (Asset 70d) from southwest corner, ranging rod demarcating northeast corner
- Plate 10-2-14: View northwest over quarry (Asset 96)
- Plate 10-2-15: Ruinous building, part of Swarclett settlement (Asset 70), immediately outwith Proposed Development Site boundary, facing southeast
- Plate 10-2-16: View southeast towards Scheduled Stone Lud (Asset 47), right of central building, from southeast boundary of the Proposed Development Site
- Plate 10-2-17: View northwest to Turbine 2 location, Swarclett (Asset 70) beyond
- Plate 10-2-18: View southeast towards the Scheduled Stone Lud (Asset 47) with intervening forestry plantation, from near Turbine 2 location
- Plate 10-2-19: Drainage ditch (Asset 110), facing north-northwest
- Plate 10-2-20: Clearance cairn (Asset 109), facing southwest
- Plate 10-2-21: View over probable clearance cairn (Asset 113), facing southwest


# Contents

Plate 10-2-22: View northwest towards Proposed Development Site overlooking the Scheduled Stone Lud (Asset 47) recumbent stone (foreground) and standing stone (mid ground)

Plate 10-2-23: View southwest overlooking the Scheduled Stone Lud (Asset 47) standing stone, illustrating the screening effect of the drystone wall and gorse on southerly views

# 1 Walkover Survey Plates

These plates supplement the archaeological walkover survey description in Chapter 10 Cultural Heritage, Section 10.3.4.





**Plate 10-2-1: View south-southwest towards the southwest portion of Site, within the topographical setting of a former river valley**



**Plate 10-2-2: View over existing track, facing east**



**Plate 10-2-3: View over the northwest extent of the Proposed Development Site with clearance cairn (Asset 103) immediately adjacent to the boundary visible in left mid-frame, facing southwest**



**Plate 10-2-4: Modern dismantled agricultural building (Asset 104), facing southwest**



Plate 10-2-5: Small clearance cairn, facing west



Plate 10-2-6: Drainage ditch (Asset 106) under vegetation on right of ranging rod, facing southwest



Plate 10-2-7: Spoil heap (Asset 107) under vegetation, facing southeast



Plate 10-2-8: View northwest over Turbine 1 location





**Plate 10-2-9: View west from Turbine 1 location towards the Scheduled Stemster long cairn (Asset 9), visible in mid-frame skyline as low mound framed by larger reservoir mound to left and commercial forestry plantation to the right**



**Plate 10-2-10: View southeast from Turbine 1 location towards the Scheduled Stone Lud (Asset 47), situated beyond (and below) intervening rise of hill**



Plate 10-2-11: Drystone wall (Asset 70a), facing southwest



Plate 10-2-12: View northeast over building (Asset 70c) from southwest corner, ranging rod demarcating northeast corner



**Plate 10-2-13: View northeast over building (Asset 70d) from southwest corner, ranging rod demarcating northeast corner**



**Plate 10-2-14: View northwest over quarry (Asset 96)**



**Plate 10-2-15: Ruinous building, part of Swarclett settlement (Asset 70), immediately outwith Proposed Development Site boundary, facing southeast**



**Plate 10-2-16: View southeast towards Scheduled Stone Lud (Asset 47), right of central building, from southeast boundary of the Proposed Development Site**



Plate 10-2-17: View northwest to Turbine 2 location, Swarclett (Asset 70) beyond



Plate 10-2-18: View southeast towards the Scheduled Stone Lud (Asset 47) with intervening forestry plantation, from near Turbine 2 location



Plate 10-2-19: Drainage ditch (Asset 110), facing north-northwest



Plate 10-2-20: Clearance cairn (Asset 109), facing southwest



Plate 10-2-21: View over probable clearance cairn (Asset 113), facing southwest



Plate 10-2-22: View northwest towards Proposed Development Site overlooking the Scheduled Stone Lud (Asset 47) recumbent stone (foreground) and standing stone (mid ground)



**Plate 10-2-23: View southwest overlooking the Scheduled Stone Lud (Asset 47) standing stone, illustrating the screening effect of the drystone wall and gorse on southerly views**

